



FAST-mask Service Schedule

PRODUCT RANGE: FAST-10, FAST-15, FAST-15-QFH & FAST-15-LW-QFH

Part Number	Description	Pack/Kit Quantity	Year 5*	Year 10
Facemask				
175-009-00	Inner Mask Valve Flap	10	Replace	Replace
175-012-00	Head Harness assembly	1	Replace	Replace
175-001-00	Facemask Service Kit	1		Replace
Demand Valve				
175-004-00	PP Demand Valve assembly (less hose)	1		Replace
175-023-00	Demand Valve Hose assembly	1		Replace
175-013-00	Demand Valve connector O-ring pack (6)	5	Replace	Replace
Cylinder Valve				
175-002-00	Valve Service Kit (DIN charging port)	1	Replace	Replace
175-003-00	Valve Service Kit (QuickFill HP connector)	1	Replace	Replace

*IMPORTANT NOTES:

This schedule covers the expected replacement of parts under normal service conditions. In addition to this schedule any parts demonstrating signs of damage and/or ageing during annual routine testing/inspection must be replaced.

Cylinders must be periodically tested in accordance with national regulations and cylinder approval standards. The FAST-mask range of cylinder/reducing valves must be fully serviced in conjunction with the required periodic testing of the cylinder to which it is fitted.

Servicing of the above product must only be carried out by authorised Cam Lock Service Centres and personnel holding a current in date Service & Maintenance Certificate, strictly in accordance with the manufacturer's instructions specified in the Product Service Manual.

For a complete range of replacement spare part components, refer to the Product Service Manual or contact a Cam Lock distributor